

ISUZU NEW ITEMS

8-98161-466-0 29Φ
8-97947-039-0 28Φ



STABILIZER BUSH

D-MAX

1012~

TFR , TFS (4x2/4x4)

8-97945-545-0



SPRING BUSH

D-MAX

1012~

TFR , TFS (4x2/4x4)

NISSAN NEW ITEMS

54445-4M400



RACK & PINION BUSH

PULSAR N16

99,12 ~ 07.09, ~






QG13DE/16DE/18DE

SUNNY N16G

08,12 ~

QG16DE

TOYOTA NEW ITEMS

<p>90385-13009</p> 	<p>STABILIZER LINK BUSH</p> <p>DYNA</p> <table> <tr> <td>00,10~02,06</td> <td>XZU302,307,342</td> </tr> <tr> <td>02,12~06,10</td> <td>BU303,343 , WU300,340 , XZU305</td> </tr> <tr> <td>02,12~08,12</td> <td>WU300,340</td> </tr> <tr> <td>02,12~03,12</td> <td>BU300,340</td> </tr> <tr> <td>06,10~11,06</td> <td>WU30#,34#</td> </tr> <tr> <td>17,07~</td> <td>WU302,342,600,650 , XZU600,650</td> </tr> </table>	00,10~02,06	XZU302,307,342	02,12~06,10	BU303,343 , WU300,340 , XZU305	02,12~08,12	WU300,340	02,12~03,12	BU300,340	06,10~11,06	WU30#,34#	17,07~	WU302,342,600,650 , XZU600,650				
00,10~02,06	XZU302,307,342																
02,12~06,10	BU303,343 , WU300,340 , XZU305																
02,12~08,12	WU300,340																
02,12~03,12	BU300,340																
06,10~11,06	WU30#,34#																
17,07~	WU302,342,600,650 , XZU600,650																
<p>48815-60170</p> 	<p>STABILIZER BUSH</p> <p>LAND CRUISER</p> <table> <tr> <td>99,08~01,08</td> <td>HZJ78,79</td> </tr> <tr> <td>99,08~08,08</td> <td>FZJ78,79</td> </tr> <tr> <td>99,08~07,01</td> <td>HZJ78,79 , FZJ78,79 , HDJ78,79</td> </tr> <tr> <td>07,01~09,07</td> <td>FZJ78,79</td> </tr> <tr> <td>07,01~16,08~</td> <td>VDJ78,79 , HZJ78,79</td> </tr> </table>	99,08~01,08	HZJ78,79	99,08~08,08	FZJ78,79	99,08~07,01	HZJ78,79 , FZJ78,79 , HDJ78,79	07,01~09,07	FZJ78,79	07,01~16,08~	VDJ78,79 , HZJ78,79						
99,08~01,08	HZJ78,79																
99,08~08,08	FZJ78,79																
99,08~07,01	HZJ78,79 , FZJ78,79 , HDJ78,79																
07,01~09,07	FZJ78,79																
07,01~16,08~	VDJ78,79 , HZJ78,79																
<p>48815-60220/60221</p> 	<p>REAR STABILIZER BUSH</p> <p>LAND CRUISER</p> <table> <tr> <td>07,09~12,01</td> <td>UZJ200 , VDJ200 , URJ200</td> </tr> <tr> <td>12,03~15,08</td> <td>VDJ200 , URJ202,20# , GRJ200</td> </tr> <tr> <td>15,08~</td> <td>VDJ200 , URJ202,20#</td> </tr> </table>	07,09~12,01	UZJ200 , VDJ200 , URJ200	12,03~15,08	VDJ200 , URJ202,20# , GRJ200	15,08~	VDJ200 , URJ202,20#										
07,09~12,01	UZJ200 , VDJ200 , URJ200																
12,03~15,08	VDJ200 , URJ202,20# , GRJ200																
15,08~	VDJ200 , URJ202,20#																
<p>48815-60250 48815-60270/60271</p> 	<p>FRONT STABILIZER BUSH</p> <p>48815-60250 35Φ</p> <p>LAND CRUISER</p> <table> <tr> <td>07,09~12,01</td> <td>VDJ200 , UZJ200 , GRJ200</td> </tr> <tr> <td>11,09~15,08</td> <td>URJ202,20# , GRJ200 , VDJ200</td> </tr> <tr> <td>15,08~</td> <td>URJ202,20# , GRJ200 , VDJ200</td> </tr> </table> <p>48815-60270/60271 34Φ</p> <p>LAND CRUISER</p> <table> <tr> <td>15,08~</td> <td>URJ200,202 , VDJ200</td> </tr> <tr> <td>17,08~18,08</td> <td>URJ20#</td> </tr> <tr> <td>16,08~18,08</td> <td>URJ200,202</td> </tr> </table> <p>LEXUS LX450D/460/570</p> <table> <tr> <td>07,11~12,02~15,09</td> <td>URJ20#</td> </tr> <tr> <td>15,09~</td> <td>URJ201 , VDJ201</td> </tr> </table>	07,09~12,01	VDJ200 , UZJ200 , GRJ200	11,09~15,08	URJ202,20# , GRJ200 , VDJ200	15,08~	URJ202,20# , GRJ200 , VDJ200	15,08~	URJ200,202 , VDJ200	17,08~18,08	URJ20#	16,08~18,08	URJ200,202	07,11~12,02~15,09	URJ20#	15,09~	URJ201 , VDJ201
07,09~12,01	VDJ200 , UZJ200 , GRJ200																
11,09~15,08	URJ202,20# , GRJ200 , VDJ200																
15,08~	URJ202,20# , GRJ200 , VDJ200																
15,08~	URJ200,202 , VDJ200																
17,08~18,08	URJ20#																
16,08~18,08	URJ200,202																
07,11~12,02~15,09	URJ20#																
15,09~	URJ201 , VDJ201																
<p>90385-18021</p> 	<p>REAR PRIING BUSH</p> <p>LAND CRUISER</p> <table> <tr> <td>99,08~01,04~07,01</td> <td>HZJ71,78,79 , FZJ71,74,78,79</td> </tr> <tr> <td>99,08~07,01</td> <td>HDJ78</td> </tr> <tr> <td>07,01~09,07</td> <td>FZJ71,76,78,79 , HZJ71,76,78,79</td> </tr> <tr> <td>07,01~16,08</td> <td>GRJ71,76,78,79 , HZJ7# , VDJ76,78,79</td> </tr> <tr> <td>16,08~</td> <td>VDJ79,HZJ76,78,79 , GRJ7# , HZJ71 , VDJ76,78,79</td> </tr> </table>	99,08~01,04~07,01	HZJ71,78,79 , FZJ71,74,78,79	99,08~07,01	HDJ78	07,01~09,07	FZJ71,76,78,79 , HZJ71,76,78,79	07,01~16,08	GRJ71,76,78,79 , HZJ7# , VDJ76,78,79	16,08~	VDJ79,HZJ76,78,79 , GRJ7# , HZJ71 , VDJ76,78,79						
99,08~01,04~07,01	HZJ71,78,79 , FZJ71,74,78,79																
99,08~07,01	HDJ78																
07,01~09,07	FZJ71,76,78,79 , HZJ71,76,78,79																
07,01~16,08	GRJ71,76,78,79 , HZJ7# , VDJ76,78,79																
16,08~	VDJ79,HZJ76,78,79 , GRJ7# , HZJ71 , VDJ76,78,79																

TOYOTA NEW ITEMS

48725-52060



REAR CARRIER BUSH

YARIS	05,08~	NCP9#
RACTIS	09,10~	NCP100

90389-14056



SPRING BUSH

LAND CRUISER	99,08~01,08~07,01	HZJ71,78,79 , FZJ71,74,78,79 , HDJ78,79
	01,08~08,08	FZJ79 , HDJ79 , HZJ79
	07,01~09,07	FZJ71,76,78,79 , HZJ71,76,78,79 , VDJ79
	07,01~16,08~	VDJ76,78

90389-22003



SPRING BUSH

LAND CRUISER	99,08~01,08	HZJ78
	99,08~06,05	FZJ78,79
	99,08~08,08	FZJ71,78,79
	99,08~07,01	HZJ71,74,78,79 , FZJ71,78,79 , HDJ78,79
	01,08~07,01	FZJ79 , HDJ79 , HZJ79
	07,01~09,07	FZJ71,76,78,79 , HZJ71,76,78,79 , VDJ79
	07,01~16,08~	VDJ76,78