

# TOYOTA NEW ITEMS

48654-BZ120



48655-BZ170



**LOWER ARM BUSH**  
**ARM NO.48068/9-BZ160**

AVANZA

11,11~15,07 F651  
11,11~15,08 F651 , F652

48702-60130



**UPPER CONTROL ROD BUSH**  
**ARM NO.48710-60150**

LAND CRUISER

07,12~08,11 GRJ200  
07,12~12,02 URJ/UZJ/VDJ200  
11,09~15,08~ GRJ/URJ/UZJ/VDJ200,URJ202

**ARM NO.48710-60121/60131**

LAND CRUISER

15,08~ URJ200 , VDJ200 , URJ202  
LEXUS LX450D/460/570  
08,07~12,01 URJ201  
12,01~15,09 URJ20#  
15,09~ URJ201 , VDJ201

48702-60140



**LOWER CONTROL ROD BUSH**  
**ARM NO.48720-60070**

LAND CRUISER

07,09~12,01 GRJ200,UZJ200  
12,02~16,01~ GRJ200,URJ202  
15,09~ URJ201,VDJ201  
LEXUS LX450D/460/570  
07,11~12,01 URJ201  
12,01~15,09 URJ20#  
15,09~ URJ201 , VDJ201

# TOYOTA NEW ITEMS

04434-60080

## FRONT AXLE GASKET KIT


**LAND CRUISER**

04,08 - 08,08 FZJ79 , 71 , 78

07,01 - 09,08 FZJ7#

07,01 - 12,08 GRJ7# , HZJ7# , VDJ7#



Without OIL SEAL AA8098E 2 Pcs




# NISSAN NEW ITEMS

|   |   |
|---|---|
| <p>55135-01J01</p>  <p>55135-01J10</p>  | <p><b>PANHARD ROD BUSH</b></p> <p><b>PATOROL</b></p> <p>Y60 87,10 ~ 91,02 TD42<br/>           91,02 ~ 93,08 HT +V/LR +V/HR +W/LR +W/HR<br/>           93,08 ~ V/LR +V/HR +W/LR +W/HR</p> <p>Y61 01,01~02,07 GEN.TB45S +GEN.TD42<br/>           02,07~03,09 GEN.TB48DE +ZD30DDTI<br/>           GEN.TB45E.MT + GEN.TD42<br/>           TB45S +TB45E.AT +ZD30DDTI</p>   |
| <p>54613-4KH0A 33 Φ</p>    | <p><b>STABILIZER BUSH</b></p> <p>D23M 16,01~17,12 EGI/C.YD25DDTI +YD25DDTI.MID/A<br/>           QR25DE +YS23</p> <p>D23X 15,02~17,04 4WD.YD25DDTI.(S.LOW.A+LOW.A<br/>           +MID.A+HIGH.B)<br/>           4WD.YD25DDTI.S.HIGH<br/>           17,04~ 4WD.CHILE.YS23.HIGH/B +<br/>           4WD.YD25DDTI.(S/LOW/A+<br/>           LOW/A+MID/A+HIGH/<br/>           DC.QR25DE +2WD.P.YD25DDTI +<br/>           2WD.P.YS23 +N.YD25DDTI +N.YS23</p> |
| <p>54613-4KH2A 19 Φ</p>    | <p><b>STABILIZER BUSH</b></p> <p>D23M 16,01~17,12 4WD.YS23.MT +YS23.AT<br/>           2WD.YS23</p> <p>D23X 16,12~17,04 BRA.YS23<br/>           17,04~ DC.LAM.QR25DE +4WD.YD25DDTI.<br/>           (S/LOW/A+LOW/A) +<br/>           4WD.YS23.LOW/A +M</p>  |
| <p>55046-0KH1A</p>   | <p><b>SPRING BUSH</b></p> <p>D23M 16,01~17,12 4WD.YD25DDDTI.(LOW/A+LOW/C)+<br/>           4WD.QR25ED+GCC.YD25DDTI.MID/<br/>           A+TD<br/>           2WD.YD25DDTI+2WD.QR25DE</p> <p>D23X 14,11~17,04~ MEX.N.QR25DE<br/>           15,04~17,04~ (SC+CHASSIS).QR25DE +<br/>           (SC+CHASSIS).YD25DDTI +SC.YS23</p>   |

# MITSUBISHI NEW ITEMS

|  |   |
|--|---|
| <p>MR-519399</p>  | <p><b>UPPER ARM BUSH</b><br/> <b>ARM NO.4010A101(LH) /4010A102(RH)</b><br/> L 200 2WD 07,09~15,03</p>   |
| <p>TEMI-9923</p>  | <p><b>FRONT COIL SPRING BUSH KIT</b><br/> TRITON 3500/4WD 06,08~10,04 KB9T</p> <p>MR-99232<sup>㊦</sup>(BUSH) ..... 1<br/> MR-99233<sup>㊦</sup>(BUSH) ..... 1<br/> MR-99237<sup>㊦</sup>(COLLAR) ..... 1<br/> MR-99237<sup>㊦</sup>(CUP) ..... 1<br/> MR-45549<sup>㊦</sup>(SEAT) ..... 1</p> |

# SUZUKI NEW ITEMS

|  |   |
|--|---|
| <p>45120-81A02/03/04</p>  | <p><b>FRONT AXLE SEAL KIT</b></p> <p>JIMMNY</p> <p>98,08~01,12 JB23W<br/> 97,12~00,03 JB33W<br/> 00,04~05,10~ JB43W</p> |
|--|---|