

A Happy New Year!
恭贺新禧!
¡Feliz Año Nuevo!



A Happy New Year!!

We really appreciate your great support that you have done for New-Era last year, too.

Last year people around the world have been afflicted by disaster due to abnormal weather. This abnormal weather caused a tornado (which is very rare in Japan), also we recorded the highest temperature in various places of Japan. Especially typhoon “Haiyan (Philippine name: Yolanda)” which hit Philippines caused unexpectedly damage. We could not treat it as being nothing with us through the experience of the Fukushima. We hope that people suffering from disaster could return to normal as soon as possible.

Signs of the economic recovery have appeared since last year as a result of “Abenomics”. We will move forward with your cooperation of all of you in order to keep up with the world trends.

This is the year of the Horse in Chinese astrology. We will challenge anything as fast as possible just like the running horse. Your continuous support will be very appreciated.

Yours sincerely.

新年快乐!!

A Happy New Year!

在过去一年中您对敝公司深切的关照表示真挚的感谢。

过去一年里全球气象异常，世界各地遭受了各种灾害。日本各地区更新了历史高温，遭遇了龙卷风，菲律宾遭遇台风「海燕」袭击受灾惨重。三年前我们经历了大地震，同样深知自然灾害的危害。祝愿受灾地区能够早日恢复重建。

通过日本过去一年的「安倍经济政策」实施，我们看到了经济复苏的征兆。在这个节点敝公司也不甘落后将与大家更加紧密合作推进业务、跟上趋势。

今年是「马年」。我们要像马儿一样，对任何事情都迅速的做出判断并尽早执行。希望您今年也会一如既往的给予我们热情的支持。

FELIZ AÑO NUEVO

AGRADECEMOS DE TODO CORAZON POR TODA SU AMABLE ATENCION BRINDADA A LO LARGO DEL AÑO 2013.

EL AÑO PASADO SE PRESENTARON VARIOS DESASTRES NATURALES EN DIFERENTES LUGARES DEL MUNDO DEBIDO A LOS FUERTES CAMBIOS CLIMATICOS. EN VARIOS LUGARES DE JAPON SE SINTIERON TEMPERATURAS MUY ALTAS QUE SUPERARON LAS DE AÑOS ANTERIORES Y QUE OCASIONARON TORNADOS, ALGO QUE NO ES MUY HABITUAL EN NUESTRO PAIS. SOBRE TODO CABE DESTACAR EL TIFON HAIVAN (YOLANDA) QUE AZOTO FILIPINAS DEJANDO ENORMES DAÑOS EN EL PAIS.

PARA NOSOTROS ESTO NO ES UN TEMA AISLADO YA QUE SUFRIMOS EL GRAN TERREMOTO HACE TRES AÑOS. ES NUESTRO DESEO DE QUE LOS DAMNIFICADOS PUEDAN RETORNAR A SUS VIDAS NORMALES DENTRO DE POCO TIEMPO.

POR OTRO LADO, EL 2013 FUE UN AÑO EN EL CUAL SE PUDO PERCIBIR SIGNOS DE UNA RECUPERACIÓN ECONOMICA, GRACIAS A LA POLITICA DENOMINADA ABENOMICS.







HAREMOS NUESTRO MEJOR ESFUERZO PARA SEGUIR ADELANTE EN EL CAMINO AL ÉXITO, SIEMPRE CON LA AYUDA DE TODOS NUESTROS CLIENTES. ESTE AÑO, SEGÚN EL HOROSCOPO CHINO, ES EL AÑO DEL CABALLO Y VAMOS A SEGUIR SU EJEMPLO ACTUANDO SIEMPRE CON LA RAPIDEZ Y EXACTITUD DE UN CABALLO DE CARRERAS.

AGRADECEMOS DE ANTEMANO POR TODO EL APOYO QUE SIEMPRE NOS HAN BRINDADO A LO LARGO DE TODA NUESTRA RELACION COMERCIAL.

北村伸雄
Nobuo Kitamura, President

<http://www.newera.co.jp/>

NEW PRODUCTS NP-216

Illustration	Ref. No.	Application	On Sale																																
<p>IVR-5022 12V</p>   <p>200PCS./CARTON CARTON SIZE: 57×34×29cm(0.056202m³) G/W:9.0kg</p>	<p>31135-RJA-A01 (126600-3150) 31150-PQK-A010M (126600-0041) (126600-0040) (126600-0042)</p> <p>ALTERNATOR 12V 110A 31100-RCB-Y020 (104210-4481) 31100-RCB-Y01 (104210-3500)</p> <p>12V 130A 31100-RJA-A010 (104210-4690) 31100-PGK-A03 (104210-3092)</p> <p>31100-RGL-A010 (104210-4290)</p>	<p>HONDA</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 30%;">INSPIRE</td> <td style="width: 15%;">UC1</td> <td style="width: 15%;">(J30A)</td> <td style="width: 10%;">'03~</td> </tr> <tr> <td>ELYSION</td> <td>RR5,RR6</td> <td>(J35A)</td> <td>'07~</td> </tr> <tr> <td>LEGEND</td> <td>KB1</td> <td>(J35A)</td> <td>'04~</td> </tr> <tr> <td>LAGREAT</td> <td>RL1</td> <td>(J35A)</td> <td>'01~</td> </tr> <tr> <td>ODYSSEY(USA)</td> <td>RL</td> <td>(J35A)</td> <td>'02~'04</td> </tr> <tr> <td>PILOT(USA)</td> <td>YF</td> <td>(J35A)</td> <td>'03~'04</td> </tr> <tr> <td>ACCORD(USA)</td> <td></td> <td>(J30A)</td> <td>'07~</td> </tr> </table> <p>ACURA</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 30%;">MDX</td> <td style="width: 15%;">YD1</td> <td style="width: 15%;">(J35A)</td> <td style="width: 10%;"></td> </tr> </table> 	INSPIRE	UC1	(J30A)	'03~	ELYSION	RR5,RR6	(J35A)	'07~	LEGEND	KB1	(J35A)	'04~	LAGREAT	RL1	(J35A)	'01~	ODYSSEY(USA)	RL	(J35A)	'02~'04	PILOT(USA)	YF	(J35A)	'03~'04	ACCORD(USA)		(J30A)	'07~	MDX	YD1	(J35A)		<p>MAR.'14</p>
INSPIRE	UC1	(J30A)	'03~																																
ELYSION	RR5,RR6	(J35A)	'07~																																
LEGEND	KB1	(J35A)	'04~																																
LAGREAT	RL1	(J35A)	'01~																																
ODYSSEY(USA)	RL	(J35A)	'02~'04																																
PILOT(USA)	YF	(J35A)	'03~'04																																
ACCORD(USA)		(J30A)	'07~																																
MDX	YD1	(J35A)																																	
<p>IVR-5023 12V</p>   <p>200PCS./CARTON CARTON SIZE: 57×34×29cm(0.056202m³) G/W:9.0kg</p>	<p>27700-20060 (126600-0022) (126600-0020) (126600-0021)</p> <p>ALTERNATOR 12V 130A 27060-20170 (104210-3042) 27060-28130 (104210-3141)</p> <p>27060-20180 (104210-3110) 27060-20190</p>	<p>TOYOTA</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 30%;">HIGHLANDER</td> <td style="width: 15%;">3.0L</td> <td style="width: 15%;">(1MZ-FE)</td> <td style="width: 10%;">'01~'03</td> </tr> <tr> <td>ALPHARD</td> <td>MNH10W/15W</td> <td>(1MZ-FE)</td> <td>'02~'03</td> </tr> <tr> <td>ESTIMA</td> <td>MCR30W/40W</td> <td>(1MZ-FE)</td> <td>'01~'03</td> </tr> <tr> <td>GAIA</td> <td>ACM10G/15G</td> <td>(1AZ-FSE)</td> <td>'02~'04</td> </tr> </table> <p>LEXUS</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 30%;">RX300</td> <td style="width: 15%;">3.0L</td> <td style="width: 15%;">(1AZ-FSE)</td> <td style="width: 10%;">'01~'03</td> </tr> </table> 	HIGHLANDER	3.0L	(1MZ-FE)	'01~'03	ALPHARD	MNH10W/15W	(1MZ-FE)	'02~'03	ESTIMA	MCR30W/40W	(1MZ-FE)	'01~'03	GAIA	ACM10G/15G	(1AZ-FSE)	'02~'04	RX300	3.0L	(1AZ-FSE)	'01~'03	<p>FEB.'14</p>												
HIGHLANDER	3.0L	(1MZ-FE)	'01~'03																																
ALPHARD	MNH10W/15W	(1MZ-FE)	'02~'03																																
ESTIMA	MCR30W/40W	(1MZ-FE)	'01~'03																																
GAIA	ACM10G/15G	(1AZ-FSE)	'02~'04																																
RX300	3.0L	(1AZ-FSE)	'01~'03																																