











**New-Era® FLASHER RELAY(INDICATOR RELAY)**  
**NEW PRODUCTS NP-242**

Illustration	Ref. No.	Application	Year	On Sale
<p><b>FLS-107</b>      <b>12V</b></p>  <p>New-Era FLS-107 12.8V 85/min TUON SIGNAL 21Wx3-SW+1.4W HAZARD WARNING 21W MAX.60LLBS http://www.newera.co.jp</p>	<p>MC867672 (066500-3301)</p>	<p><b>MITSUBISHI</b> CANTER      FE</p>  <p>※12TERMINAL 6PIN</p>	'93~	NOV.'16
<p><b>FLS-108</b>      <b>12V</b></p>  <p>New-Era FLS-108 12.8V 85/min TUON SIGNAL 21Wx3-SW+1.4W HAZARD WARNING 21W MAX.60LLBS http://www.newera.co.jp</p>	<p>MC857354 MC857345 MK327447 (066500-3132) (066500-3133) (066500-4540)</p>	<p><b>MITSUBISHI</b> CANTER      FE</p>  <p>※12TERMINAL 10PIN</p>	'96~	NOV.'16
<p><b>NPR-103</b>      <b>12V</b></p>  <p>New-Era® NPR-103 87 → 30 87 → 30 86 → 85 12V 30A</p>	(0 332 019 150)	<p><b>UNIVERSAL</b> Rated Current      30A</p> 		NOV.'16

<http://www.newera.co.jp/>



# NEW PRODUCTS

New-Era No.	Parts No.	Car Maker	Car Model	Model No.	Engine Model	Year
<b>MIC-N3062</b> 	22448-31U05 22448-31U06 22448-31U15 22448-31U16	<b>NISSAN</b> CEFIRO		A32	(VQ20,VQ25, VQ30)	'94~'99
		<b>INFINITI</b> I30	MAXIMA	A32		
<b>MIC-N3063</b> 	22448-31U00 22448-31U01 22448-31U11	<b>NISSAN</b> CEFIRO		A32	(VQ20,VQ25, VQ30)	'94~'99
		<b>INFINITI</b> I30	MAXIMA	A32		
<b>MIC-H3064</b> 	30520-R70-S01 30520-R70-A01	<b>HONDA</b> ODYSSEY ACCORD CROSSTOUR			(3.5L) (3.5L)	'08~'14 '08~'12 '10~'12
		<b>ACURA</b> RL TL TSX				
<b>MIC-T3065</b> 	19500-B2040 19500-B1010	<b>DAIHATSU</b> ATRAI WAGON SONICA TANTO(CUSTOM) HIJET		S321G,S331G L405S,L415S L375S,L385 S321V,S331V, S321W,S331W		
		MIRA(CUSTOM) MOVE(CUSTOM) MOVE CONTE (CUSTOM)		L275S,L285S, L285S L175S,L185S L575S,L585S		