

2012

HITACHI
Inspire the Next

TOKICO

NEW MODEL INFORMATION

2012/7/1

<http://www.tokico.biz>



COMFORTABLE DRIVING WITH HIGH QUALITY SHOCKS

※Some models may have different part No. even in same model and year.
Please confirm OEM No. before you place an order.

NEW ADDITIONAL ITEMS

**【P. 6 TOYOTA : IST】
B2254**

This item is started to deliver from the end of November, 2012.

TOKICO SHOCK ABSORBERS NEW MODEL INFORMATION

2012/7/1

Yellow highlighted stock numbers are new items.

Pink highlighted stock numbers are changed to new stock number.

Green highlighted stock numbers are compatible stock number or model.

Beige highlighted cells are revised.

NISSAN

YEAR	MODEL	FRONT				REAR			
		R. L.	OIL	GAS	OEM NO.	R. L.	OIL	GAS	OEM NO.

LIVINA GENISS/GRAND LIVINA (P115)

07/02~10/11	L10N (STD..1500..AT) (1500..MT) (1800) GRAND LIVINA for Indonesia	R		B2336	E4302-CJ41B				E6210-CJ41C
		L		B2337	E4303-CJ41B				
11/02~	L10N (STDB..1500) (STD..1500..AT) (1500..MT) (1800) GRAND LIVINA for Indonesia	R		B2322	E4302-CJ41C		E20033		E6210-CJ45E
		L		B2323	E4303-CJ41C				
07/09~	L10L (1600) (1800) GRAND LIVINA for Malaysia	R		B2336	E4302-CJ41B				E6210-CJ41C
		L		B2337	E4303-CJ41B				
07/08~	TL10N (1500) LIVINA Made in Indonesia	R			E4302-CJ40B				E6210-CJ40C
		L			E4303-CJ40B				
08/08~	NL10S (1600) L10S (3ROW..1600..HI.MT) L10S (2ROW..1600) LIVINA Made in South Africa	R			E4302-CJ40B				E6210-CJ40C
		L			E4303-CJ40B				
07/10~	L10S (3ROW..1600..HI.MT) LIVINA Made in South Africa	R		B2336	E4302-CJ41B				E6210-CJ41D
		L		B2337	E4303-CJ41B				
11/06~	NTL10L (1600) LIVINA XGEAR for Malaysia	R			E4302-CJ45A				E6210-CJ45A
		L			E4303-CJ45A				
08/04~	NTL10N (1500) LIVINA XGEAR for Indonesia	R		B2322	E4302-CJ40C				E6210-CJ40D
		L		B2323	E4303-CJ40C				
08/04~	L10P (1800) GRAND LIVINA for Philippines	R		B2322	E4302-CJ41C				E6210-CJ41C
		L		B2323	E4303-CJ41C				
10/03~	L10H (1800) GRAND LIVINA for Vietnam	R		B2336	E4302-CJ41B		E20033		E6210-CJ45E
		L		B2337	E4303-CJ41B				
09/01~	L10B (1600) (1800) LIVINA Made in Brazil	R			E4302-AZ60B				E6210-AZ60B
		L			E4303-AZ60B				
09/04~	L10B (1800..AT.4F) (1800..MT.6F) LIVINA Made in Brazil	R			54302-AZ61B				E6210-AZ61B
		L			54303-AZ61B				
08/03~	NL10Z (1600) LIVINA C-GEAR Left-hand drive	R		B2336	54302-CJ00B				E6210-CJ05B
		L		B2337	54303-CJ00B				
07/04~	L10Z (1600) LIVINA GENISS Left-hand drive	R		B2336	54302-CJ00B				E6210-CJ05B E6210-CJ00C
		L		B2337	54303-CJ00B				
06/11~06/12	L10Z (1800..MT.6F) (1800..AT.4F) LIVINA GENISS Left-hand drive	R		B2336	54302-CJ01D				E6210-CJ01D
		L		B2337	54303-CJ01D				

TOKICO SHOCK ABSORBERS NEW MODEL INFORMATION

2012/7/1

Yellow highlighted stock numbers are new items.

Pink highlighted stock numbers are changed to new stock number.

Green highlighted stock numbers are compatible stock number or model.

Beige highlighted cells are revised.

YEAR	MODEL	FRONT				REAR					
		R	L	OIL	GAS	OEM NO.	R	L	OIL	GAS	OEM NO.
06/12~07/02	L10Z (1800..MT. 6F) (1800..AT. 4F) LIVINA GENISS Left-hand drive	R			B2336	54302-CJ01D					E6210-CJ01E
		L			B2337	54303-CJ01D					
07/02~07/05	L10Z (1800..MT. 6F) (1800..AT. 4F) LIVINA GENISS Left-hand drive	R			B2336	54302-CJ01D					E6210-CJ02A
		L			B2337	54303-CJ01D					
07/05~	L10Z (1800) LIVINA GENISS Left-hand drive	R			B2336	54302-CJ01D					E6210-CJ05A E6210-CJ02B
		L			B2337	54303-CJ01D					

TIIDA/TIIDA LATIO (P126) *Additional model and genuine part numbers are written in red.

04/09~06/12	C11, SC11, JC11, SJC11 (1500, 1800)	R			B2322	54302-ED001 54302-ED00A	E4302-ED00A				E20020	56210-ED001 56210-ED025 56210-ED00A E6210-ED05A E6210-ED00A	
		L			B2323	54303-ED001 54303-ED00A	E4303-ED00A						
06/12~08/01	C11, SC11, JC11, SJC11 (1500, 1800)	R			B2322	54302-EU50A 54302-EU51A	E4302-EU50A E4302-EU51A				E20020	56210-ED50A E6210-EU50A	
		L			B2323	54303-EU50A 54303-EU51A	E4303-EU50A E4303-EU51A						
08/01~09/09	C11, SC11, JC11, SJC11 (1500, 1800)	R			B2322	E4302-EU51A E4C02-EU51A					E20020	56210-ED001 E6210-EU51A	
		L			B2323	E4303-EU51A E4C03-EU51A							
09/09~10/08	C11, SC11, JC11, SJC11 (1500, 1800)	R			B2322	E4302-EU51A E4C02-EU51A					E20020	E6210-EU55A E6210-EU56A E6210-EU57A E6B10-EU57A	
		L			B2323	E4303-EU51A E4C03-EU51A							
10/08~	C11 (1500) .. 4AT	R			B2322	E4C02-EU51A E4C02-1J60A					E20020	E6B10-EU56B E6210-1J60B	
		L			B2323	E4C03-EU51A E4C03-1J60A							
10/08~	C11 (1500) .. CVT	R				E4C02-1J60A						E6210-1J60A	
		L				E4C03-1J60A							
10/08~	C11 (1500) , SC11 (1500) .. CVT	R			B2322	E4C02-EU51A E4302-1J60A						E6B10-EU57A E6210-1J60B	
		L			B2323	E4C03-EU51A E4303-1J60A							
04/09~06/02	NC11, SNC11 (1500 4WD)	R			B2322	54302-ED001 54302-ED002	54302-ED025					E20020	56210-ED001 56210-ED301 56210-ED325
		L			B2323	54303-ED001 54303-ED002	54303-ED025						
06/02~06/12	NC11, SNC11 (1500 4WD)	R			B2322	54302-ED001 54302-ED025							56210-ED30A E6210-ED30A E6210-ED35A
		L			B2323	54303-ED001 54303-ED025							
06/12~08/01	NC11, SNC11 (1500 4WD)	R			B2322	54302-EU50A 54302-EU51A E4302-EU50A	E4302-EU51A						56210-ED50B E6210-EU50B
		L			B2323	54303-EU50A 54303-EU51A E4303-EU50A	E4303-EU51A						
08/01~10/08	NC11, SNC11 (1500 4WD)	R			B2322	E4302-EU51A E4C02-EU51A					E20020	56210-ED001 E6210-EU51B E6210-EU55B E6210-EU56B E6B10-EU56B	
		L			B2323	E4303-EU51A E4C03-EU51A							
10/08~	SNC11 (1500 4WD)	R				E4302-1J60A						E6210-1J60B	
		L				E4303-1J60A							

TOKICO SHOCK ABSORBERS NEW MODEL INFORMATION

2012/7/1

Yellow highlighted stock numbers are new items.

Pink highlighted stock numbers are changed to new stock number.

Green highlighted stock numbers are compatible stock number or model.

Beige highlighted cells are revised.

YEAR	MODEL	FRONT				REAR				
		R/L	OIL	GAS	OEM NO.	R/L	OIL	GAS	OEM NO.	
06/12~08/01	C11, SC11 (1500) for Hong Kong	R		B2322	54302-ED001 54302-ED00A E4302-ED00A				E20020	56210-ED001 56210-ED00A E6210-ED00A E6210-ED05A
		L		B2323	54303-ED001 54303-ED00A E4303-ED00A					
05/04~06/04	C11Z(1600) Made in China for China	R		B2322	54302-ED001 54302-ED50B				E20020	56210-ED001 56210-ED525
		L		B2323	54303-ED001 54303-ED50B					
06/04~08/01	C11Z(1600) Made in China for China	R		B2322	54302-ED50B					E6210-ED50C E6210-ED50D
		L		B2323	54303-ED50B					
08/01~11/04	C11Z(1600) Made in China for China	R		B2336	54302-CJ01D					E6210-CJ02B E6210-CJ05A
		L		B2337	54303-CJ01D					
05/08~08/06	C11(1600, 1800) Made in Japan for left-hand drive for global country	R		B2322	54302-ED001 E4302-EE90A E4C02-EE90A				E20020	56210-ED001 E6210-EE90A E6210-EE90B E6B10-EE90B
		L		B2323	54303-ED001 E4303-EE90A E4C03-EE90A					
08/06~10/08	C11(1600..U, 1800) Made in Japan for left-hand drive for Gulf Cooperation Council countries	R			E4302-1JY0A E4C02-1JY0A				E20020	56210-ED001 E6210-EE90B E6B10-EE90B
		L			E4303-1JY0A E4C03-1JY0A					
08/06~10/08	C11(1600..BP) Made in Japan for left-hand drive for Gulf Cooperation Council countries	R		B2322	E4302-EE90A E4C02-EE90A				E20020	56210-ED001 E6210-EE90B E6B10-EE90B
		L		B2323	E4303-EE90A E4C03-EE90A					
06/06~	C11X(1800) Made in Mexico	R		B2322	54302-ED001 E4302-EL00A E4302-EL20A	E4C02-EL00A				E6210-EL00A E6B10-EL00A
		L		B2323	54303-ED001 E4303-EL00A E4303-EL20A	E4C03-EL00A				
07/01~	C11X(1800) for left-hand drive for global country	R		B2322	54302-ED001 E4302-EL00A					E6210-EL00A
		L		B2323	54303-ED001 E4303-EL00A					
09/03~	C11X(Diesel) Made in Mexico SC11X(Diesel) for left-hand drive for global country	R		B2322	E4302-EM20B					E6210-ZW70A
		L		B2323	E4303-EM20A					
06/04~	C11, SC11 (1500, 1600, 1800) Made in Japan for right-hand drive for global country	R		B2322	54302-ED001 54302-EU51A E4302-ED00A E4302-EU51A	E4302-EE90A			E20020	56210-ED001 E6210-ED00A 56210-EU51A E6210-EU51A E6210-EE90B
		L		B2323	54303-ED001 54303-EU51A E4303-ED00A E4303-EU51A	E4303-EE90A				
06/06~	C11S, SC11S(1600, 1800) Made in South Africa for right-hand drive	R		B2322	54302-ED001 E4302-EE40A				E20020	56210-ED001 E6210-EE40A
		L		B2323	54303-ED001 E4303-EE40A					
06/05~	C11T, SC11T(1600, 1800) Made in Thailand for right-hand drive for global country	R		B2322	E4302-EE50A E4302-EE50B					E6210-EE50B E6210-EE50C E6210-EE50E
		L		B2323	E4303-EE50A E4303-EE50B					
05/12~	C11, SC11(1800) Made in Japan for Australia	R		B2322	54302-EE90A E4302-EE90A				E20020	56210-EE90B E6210-EE90B
		L		B2323	54303-EE90A E4303-EE90A					

TOKICO SHOCK ABSORBERS NEW MODEL INFORMATION

2012/7/1

Yellow highlighted stock numbers are new items.

Pink highlighted stock numbers are changed to new stock number.

Green highlighted stock numbers are compatible stock number or model.

Beige highlighted cells are revised.

YEAR	MODEL	FRONT				REAR			
		R. L.	OIL	GAS	OEM NO.	R. L.	OIL	GAS	OEM NO.
06/10~	C11T, SC11T(1800) Made in Thailand for Australia	R		B2322	E4302-EE50A E4302-EE50B				E6210-EE50B E6210-EE50C E6210-EE50E
		L		B2323	E4303-EE50A E4303-EE50B				
07/02~	C11X, SC11X(1600, 1800, Diesel) Sedan for right-hand drive for Europe	R		B2322	54302-ED001 E4302-EM01A E4302-EM20A			E20020	E6210-EM01A E6210-EM20A
		L		B2323	54303-ED001 E4303-EM01A E4303-EM20A				
07/02~07/08	C11X, SC11X(1600, 1800, Diesel) Sedan & Hatchback for left-hand drive for Europe	R		B2322	54302-ED001 E4302-EM01A E4302-EM20A			E20020	E6210-EM01A E6210-EM20A
		L		B2323	54303-ED001 E4303-EM01A E4303-EM20A				
07/08~	C11X(1600, 1800) Sedan & Hatchback for left-hand drive for Europe	R		B2322	54302-ED001 E4302-EC80A				E6210-EC80A
		L		B2323	54303-ED001 E4303-EC80A				
05/08~08/06	LAT10 SC11(1600, 1800) for left-hand drive for global country	R		B2322	54302-ED001 E4302-EE90A			E20020	56210-ED001 E6210-EE90A E6210-EE90B
		L		B2323	54303-ED001 E4303-EE90A				
08/06~	LAT10 SC11(1800) for right-hand drive for global country& for left-hand drive for Gulf Cooperation Council Countries	R			E4302-1JY0A			E20020	56210-ED001 E6210-EE90B
		L			E4303-1JY0A				
07/04~	LAT10 C11L(1600, 1800) Made in Malaysia for right-hand drive for global country	R		B2322	E4302-EE50A E4302-EE50B				E6210-EE50C E6210-EE50E
		L		B2323	E4303-EE50A E4303-EE50B				

TOYOTA

YEAR	MODEL	FRONT				REAR			
		R. L.	OIL	GAS	OEM NO.	R. L.	OIL	GAS	OEM NO.
CAMRY/CAMRY GRACIA (P149)									
01/10~03/07	ACV30 2.4L/MCV30 3.0L	R		B3330	48510-33402 48510-33412 48510-33432 48510-80037 48510-80146 48510-80147 48510-80149 48510-AA040	R		B3214	48530-06240 48530-06240C 48530-06260 48530-06260C 48530-09M50 48530-33282 48530-33292 48530-33302 48530-80164 48530-80165 48530-80166 48530-A9120 48530-A9130 48530-AA040 48530-AA070
		L		B3331	48520-33402 48520-33412 48520-33432 48520-39685 48520-39695 48520-39715 48520-AA040	L		B3214 ↓ B3215	48540-06240 48540-06240C 48540-06260 48540-06260C 48540-33282 48540-33292 48540-33302 48540-39605 48540-39615 48540-39625

CAMRY/AVALON/SCEPTEP/VIENTA/LEXUS ES300 (WINDOW) (P151)

03/02~	MCV30(3000 2WD) Electronic Suspension	R		B3332	48510-33401 48510-33411 48510-33421 48510-33431 48510-33480 48510-33490 48510-80108 48510-80117 48510-80118 48510-80119 48510-80163 48510-80165	R		B3324	48530-33281 48530-33291 48530-33301 48530-33340 48530-39885 48530-80111 48530-80112 48530-80196
		L		B3333	48520-33401 48520-33411 48520-33421 48520-33431 48520-33480 48520-33490 48520-39545 48520-39565 48520-39575 48520-39595 48520-39735 48520-80013	L		B3325	48540-33281 48540-33291 48540-33301 48540-33340 48540-39465 48540-39485 48540-39495 48540-39635

TOKICO SHOCK ABSORBERS NEW MODEL INFORMATION

2012/7/1

Yellow highlighted stock numbers are new items.

Pink highlighted stock numbers are changed to new stock number.

Green highlighted stock numbers are compatible stock number or model.

Beige highlighted cells are revised.

YEAR	MODEL	FRONT				REAR			
		R. L.	OIL	GAS	OEM NO.	R. L.	OIL	GAS	OEM NO.

HI ACE (include VAN, WAGON, COMMUTER) (P175)

89/08~92/05	LH109, 119, 129		3474	E3474	48511-29595				48531-80401
89/08~95/08	LH107		3474	E3474	48511-29605				48531-80404
89/08~95/08	LH117 (4WD Wagon)		3474	E3474	48511-29605				48531-80416
93/08~95/08	KZH100/101G, LH100/101G, RZH100/101G for Mexico		3529		48511-26240 48511-26280 48511-26282 48511-26320 48511-29525 48511-29527 48511-29566 48511-29575 48511-29676 48511-29686 48511-29696 48511-80056 48511-80058	48511-26241 48511-26281 48511-26290 48511-26330 48511-29526 48511-29565 48511-29567 48511-29675 48511-29685 48511-29695 48511-80055 48511-80057		E3365	48531-26310 48531-80138 48531-80428 48531-26480 48531-26311 48531-80402 48531-80530 48531-80538

IST (P179) *Additional genuine part numbers are written in red.

02/04~07/07	NCP60 (1300)			B2254	48510-59555 48510-52610	48510-52480 48510-59765			48530-59655 48530-80192	48530-52550
02/04~07/07	NCP61 (1500)			B2254	48510-59565 48510-52610	48510-52490 48510-59765			48530-59645 48530-80193	48530-52540
04/05~07/07	NCP61 (1500) L, AERO, AERO-S				48510-80164	48510-52800			48530-80194	48530-52A60
02/04~07/07	NCP65 (1500 4WD)				48510-59575	48510-52500			48530-59635	48530-52560
07/07~10/08	ZSP110 (1800)	R		B3293	48510-80379 48510-80377	48510-52E00 48510-52D90		E20028	48530-80437	48530-52E10
		L		B3294	48520-59445 48520-59425	48520-52280 48520-52270				
07/07~	NCP110 (1500)	R		B3293	48510-80377	48510-52D90		E20028	48530-80435	48530-52E00
		L		B3294	48520-59425	48520-52270				
07/07~	NCP115 (1500 4WD)	R		B3281	48510-80378	48510-52E10			48530-80436	48530-52E40
		L		B3282	48520-59435	48520-52290				

RAV-4/VANGUARD (P187)

07/06~	ACA31W, 36W, 33W, 38W, GSA33W	R		B3245	48510-80366	48510-42300		E3824	48531-42220
		L		B3246	48520-80130	48520-42300			